


## **BUILDING SAFETY CERTIFICATE**

Certify that I have inspected the buildings, mentioned below and the same are found structurally sound to be used as academic building. The structural soundness of the building has been verified taking into account as per relevant IS codes relating to standard loading, R.C.C./C.C. specifications etc. with earthquake resistant provision.

The existing buildings in "Ramakrishna Mission School", Bachaspati Leikai, Uripok, Imphal-795001, Manipur, which are situated at the following Patta No. 199 C.S. Dag No. 2159 measuring an area of 2.0800 hectare of the village No. 91 (A) - Lamphelpat, are recently constructed with the following scopes.


- 1) R.C.C. footing
- 2) R.C.C. column
- 3) R.C.C. Grade beam, Plinth Beam, Lintel bend and Roof bend
- 4) Filler half Brick wall
- 5) Roofing - DYNA roofing over Tubular truss
- 6) Flooring - Tile/C.C.
- 7) Separate toilet for boys and girls

Date: 14-08-2020

  
**(Ch. Bishwachandra Singh)**  
Executive Engineer  
NEC-II Divn. PWD, Manipur

**(CH. BISHWACHANDRA SINGH)**  
Executive Engineer  
NEC-II Divn. PWD, Manipur

  
Principal  
Ramakrishna Mission School  
Uripok, Imphal, Manipur-795001

  
Secretary  
Ramakrishna Mission School  
Uripok, Imphal, Manipur-795001